

# Porsche 944 951 968 Spare Parts and Cross Reference

26.05.2009

NEW ITEM

| Part                         | Clarification MY         | Other cars      | Manf. Part #                 | Porsche #  | €    | Manufacturer / Other   |
|------------------------------|--------------------------|-----------------|------------------------------|--|------|------------------------|
| Engine                       |                          |                 |                              |  |      |                        |
| Fuel pressure regulator      | FPR, 2,5bar              | 944/951 85.5-89 | 0 280 160 227                | 944 110 198<br>04  | 100€ | Bosch                  |
| Fuel pressure regulator      | FPR, 3bar                | 951 85.5-89     | BMW 325 E30 85-91            |  | 100€ | Bosch, for chipped car |
|                              |                          |                 | 0 280 160 249                |  | 100€ | Bosch, for chipped car |
| Fuel pressure regulator      | FPR, 3,8bar              | S2/968          | 0 280 160 287                |  |      | Bosch                  |
| Cut-Off Valve / BOV / Bypass |                          | 951             | Saab 9-5 (part# 4441895)     | 0 280 142 110  | 30e  | Bosch                  |
| Cut-Off Valve / BOV / Bypass |                          | 951             | Newer Audi / VW              | 0 280 142 115  | 49€  | Bosch                  |
| Air filter                   |                          | 944 82-89       | VW Corrado 1.8 16V 4/89-7/92 |  | 6€   |                        |
| Radiator fan switch          | 3-pole 95°-85°+102°-92°C | 82-91           | Audi 100 88-94               | 7.5635   |      | Facet                  |
|                              |                          |                 | Seat Ibiza 93-94             | PORSCHE:951 606 481 00, VOLVO:3448916-1, VOLVO:3451216-0, VW:191 959 481 A, VW:191 959 481 C, VW:251 919 481 C, VW:251 919 481 D, VW:321 959 481 A, VW:321 959 481 C |      | FAE 37820              |
|                              |                          |                 | VW Golf II 85-91             | 968  |      |                        |
|                              |                          |                 | Volvo 400-s                  |  |      |                        |
| Expansion tank cap           | 17mm/15lbs               | 82-85.0         | Alfa 33 1,7-16V 87-92        |  |      |                        |
|                              |                          |                 | Audi 100 67-78               |  |      |                        |
|                              |                          |                 | Ford Granada 2,5-Diesel      |  |      |                        |

## Porsche 944 951 968 Spare Parts and Cross Reference

|                           |                      |                            |   |                                  |                |                             |
|---------------------------|----------------------|----------------------------|---|----------------------------------|----------------|-----------------------------|
| Throttle position sensor  |                      | 944 82-89                  |   | 0 280 120 308                    | 944 606 113 01 | Bosch                       |
| Throttle position sensor  |                      | 951                        | Volvo 440 1.7 Turbo 9/87-7/91   | 0 280 120 400                    | 951 606 113 00 | Bosch                       |
| Throttle Position sensor  |                      | 968                        | Alfa 145 / Saab 9000<br>Volvo 480 E/L 960 90-94<br>Volvo 960 2.0 8/90-9/93                    | 0 208 122 001/4                  | 944 606 116 00 | Bosch                       |
| Crank pilot bearing       |                      |                            |   | 6202-2RS/C3/FAG                  |                | FAG                         |
| DME temperature sensor    | DME, blue M12x1,5    | 82-91<br>968               | BMW 316i<br><br>Fiat Uno Fire-ie/Turbo/ie<br>Opel Astra 8V injection<br>Volvo 700-s Turbo -84 | 0 280 130 026                    | 944 605 125 00 | Bosch                       |
| Knock sensor              |                      | 951, 944S,<br>944S2<br>968 | Ford Escort 1.6 80-85<br><br>Citroen BX 19GTi 16V 87-93<br>Saab 900i-16V 85-93                | 0 261 231 006                    |                | Bosch                       |
| Speed / Reference sensors | Speed / Ref. Sensors | 82-91<br>968               | 12141708619 BMW   | 0 261 210 003                    |                | 8v 2pce, 16v 1pce           |
| Thermostat                | 83°                  | 82-88                      |   | G4000-23460<br>234-82<br>1026-80 |                | Wahler<br>Motorad<br>Vernet |
| Thermo-pneumatic valve    |                      | 951                        | Audi 100 77-91  | 058 131 851 A                    | 058 131 851 A  |                             |
| Idle control valve, ICV   |                      | 944/951                    | 85.5-89 Peugeot 405 1,9GRi<br><br>Renault R19 1,7iKat   | 0 280 140 501                    |                | Bosch                       |

## Porsche 944 951 968 Spare Parts and Cross Reference

Renault Clio-I 16V-1,8/2,0  
Volvo 740 B200ET/230ET -  
87

|                                    |                      |   |  |                   |  |
|------------------------------------|----------------------|---|--|-------------------|--|
| Idle control valve,<br>ICV         | S2                   |   | 0 280 140 531  |                   | Bosch  |
| Idle Control<br>Valve              | 968                  |   | 0 280 140 536  |                   | Bosch  |
| Cooling hose                       | 951                  | Peugeot 205 D/1,6/1,9<br>waterpump  |  | 951 106 239<br>01 |  |
| Oil filter                         | 82-91                | I   | OC142<br>OC75<br>W719/22<br>H 14 W 25<br>R 128<br>FT 5239<br>PH-6941 | 944 107 201<br>90 | Knecht / Mahle,<br>orig.<br>Knecht / Mahle,<br>longer<br>Mann<br>Hengst<br>Tecnocar<br>Fiaam<br>Fram |
|                                    | 968                  |   | 0 451 103 213  | 944 107 201<br>08 | Bosch  |
| <b>Fuel system<br/>and exhaust</b> |                      |   |  |                   |  |
| Oxygen sensor,<br>lambda           | 85.5-91              |   | 0 258 003 012  | 951 606 135<br>0  | Bosch  |
| Oxygen sensor,<br>lambda           | 968                  | Alfa 155 92-97<br>Audi A4 B5  | 0 258 003 011  | 944 606 135<br>02 | Bosch  |
| Fuel pump                          | 944 85.5-88,<br>S/S2 | Alfa 75 1,8 Turbo 87-89<br>Fiat Uno Turbo-1,3ie/1,4ie<br>85-92<br>Renault Espace 2,0i/2,2i/2,8i | 0 580 464 028  | 944 608 102<br>06 | Bosch, green   |

## Porsche 944 951 968 Spare Parts and Cross Reference

|               |                    |                     |  |               |                               |
|---------------|--------------------|---------------------|--|---------------|-------------------------------|
|               |                    |                     | 91-96<br>Volvo 343<br>B19E/B200E/B200F                   |               |                               |
| Fuel pump     |                    | 944 82-85.0,<br>951 |  | 0 580 464 021 | 944 608 102<br>04 Bosch, blue |
| Fuel filter   | <u>M14 threads</u> | 82-91               | BMW 320i 4.79-82<br>BMW 323i 9.78-8.79<br>BMW 518i 75-79 |               |                               |
| Fuel tank cap |                    | 82-91               | Audi, Passat, Golf I                                     |               |                               |

### Transmission

|                               |  |       |                         |            |                             |
|-------------------------------|--|-------|-------------------------|------------|-----------------------------|
| Clutch master cylinder gasket |  | 82-91 |                         | PBR K7664X |                             |
| Clutch slave cylinder gasket  |  | 82-91 | MB W123/124 (FAG) 76-95 | PBR 1021S  | Has to be modified slightly |

### Front axle and steering

|                             |                   |         |   |           |     |
|-----------------------------|-------------------|---------|---|-----------|-----|
| Balljoint, lower            | Steel control arm | 82-85.0 | VW Golf I   |           | 12€ |
| Control arm                 | Steel control arm | 82-85.0 | VW Golf I   |           | 23€ |
| Shock absorber cover rubber |                   | 82-85.0 | BMW 316/318/320 E21 75-82 front<br>Mercedes Benz W124 front<br>Nissan Sunny N13/B12 rear<br>VW Golf 73-91 |           |     |
| Wheel bearing,              |                   | 82-86   |   | VKBA 1400 | SKF |

## Porsche 944 951 968 Spare Parts and Cross Reference

front

|  |         |       |                     |          |  |        |
|--|---------|-------|---------------------|----------|--|--------|
|  |         | 87-91 |                     | VKBA 956 |  | SKF    |
|  | Outer   | 87-91 | L68149 99402 L68111 |          |  | Timken |
|  | Inner   | 87-91 | 1-M12649 1-M12610   |          |  | Timken |
|  | Sealing | 87-91 | ERIKS RST 45 62 10  |          |  |        |

|                    |         |       |  |  |  |  |
|--------------------|---------|-------|--|--|--|--|
| Powersteering belt | L=950mm | 82-91 | Audi 80 1,3-1,8 86-92 LA/VP<br>Honda Civic 1.2/1.3 80-83 LA/VP<br>Seat Toledo 1.6-2.0 -93 LA<br>VW Golf 1.6/1.8 86-91 LA<br>Opel Vectra B TurboD-1,7 96-OT |  |  |  |
|--------------------|---------|-------|--|--|--|--|

|                     |  |       |           |                 |  |  |
|---------------------|--|-------|-----------|-----------------|--|--|
| Power Steering Pump |  | 1980> | BMW E30 > | 32 41 1 135 880 |  |  |
|---------------------|--|-------|-----------|-----------------|--|--|

|                |               |                              |                          |              |                |           |
|----------------|---------------|------------------------------|--------------------------|--------------|----------------|-----------|
| Tie rod, outer | Powersteering | 82-86                        | Golf I, Jetta I, Caddy I | 171 419 812  | 944 347 333 00 | TRW       |
|                | Manual        | 82-83<br>94DN402644<br>until |                          | 116 020 3226 | 944 347 333 00 | Meyle     |
|                |               |                              |                          | 10251        | 944 347 333 00 | Lemförder |

### Rear axle

|                     |  |         |                     |          |  |     |
|---------------------|--|---------|---------------------|----------|--|-----|
| Wheel bearing, rear |  | 82-85.0 | VW beetle 1302/1303 | VKBA 592 |  | SKF |
|                     |  | 85.5-91 |                     | 305988   |  | SKF |
|                     |  |         |                     | 527243BE |  | FAG |
| Rear control arm    |  | 82-85.0 | VW beetle 1302/1303 |          |  |     |

## Porsche 944 951 968 Spare Parts and Cross Reference

|  |       |           |   |                              |
|--|-------|-----------|---|------------------------------|
| CV joint                                       |       | 82-86     | VW Transporter 68-90,<br>Syncro 85-90                                   | Lobro 302277<br>Spidan 21896 |
| CV joint cover<br>rubber                       |       | 82-91     | VW Transporter 68-90,<br>Syncro 85-90                                   |                              |
|  |       | 82-91     | BMW 700   |                              |
| <b>Wheels and<br/>brakes</b>                   |       |           |   |                              |
| Brake caliper<br>seals                         | Front | 944 82-89 | Audi 100 5E-2.2/TD-2.0<br>1977-7.79<br>Peugeot 505<br>Peugeot 604 front | ATE                          |
| Brake caliper<br>piston                        | Front | 944 82-89 | Peugeot 504 78-82 front<br>Peugeot 505 front<br>Peugeot 604 front       | ATE                          |
| Brake master<br>cylinder                       |       | 82-91     | MB W123   |                              |
| Emergency<br>brake shoes                       |       | 82-91     | BMW e28 525i 81-88  | Re-use old springs           |
| <b>Handlever<br/>system,<br/>pedal cluster</b> |       |           |   |                              |
| Brake and clutch<br>pedal pad                  |       | 85.5-91   | Golf II   |                              |

## Porsche 944 951 968 Spare Parts and Cross Reference

### Body and interior

|                      |       |          |                  |       |
|----------------------|-------|----------|------------------|-------|
| Sun visor clip       | 82-91 | Golf III | 3B0 857 561 BY20 | Grey  |
|                      |       |          | 3B0 857 561 BB41 | Black |
|                      |       |          | 3B0 857 561 B8YS | Beige |
| Sun visor cover-clip | 82-91 | Golf III | 3B0 857 563 BY20 | Grey  |
|                      |       |          | 3B0 857 563 BB41 | Black |
|                      |       |          | 3B0 857 563 B8YS | Beige |

### Electrical equipment

|                                   |      |         |   |                          |
|-----------------------------------|------|---------|---|--------------------------|
| Battery                           | 64Ah | 82-91   | Audi 100, gasoline 75-90<br>Seat Ibiza, 93-98<br>VW Golf III, gasoline      |                          |
| DME-relay                         |      | 82-91   | Opel  | 4RP 008 189-051<br>Hella |
| Headlamp                          |      | 82-91   | Audi 80 5/75 – 7/76<br>VW Golf I<br>VW Passat 5/73 – 7/77                   | 20e                      |
| Voltage regulator 115A alternator |      | 82-91   | Audi 100, 81-92<br>BMW 300s, 81-90<br>Ford Sierra, 82-93<br>VW Golf 8.81-91 | 1 197 311 040<br>Bosch   |
| Alternator                        | 90A  | 82-85.0 | Ford Scorpio 2,0-OHC/Diesel/TurboD 90A<br>Ford Sierra 1,3-2,0 OHC 90A       |                          |

## Porsche 944 951 968 Spare Parts and Cross Reference

|                               |          |         |   |                         |
|-------------------------------|----------|---------|---|-------------------------|
| Alternator                    | 115A     | 85.5-91 | 0 120 468 005   | Bosch, or 0 120 468 004 |
| Alternator brushes            | 5x8x15mm | 82-85.0 | MB W123 76-80<br>VW Golf 74-7.81 Bosch<br>Volvo 200-s 74-8.81   | Bosch                   |
| Alternator brushes            | 5x8x19mm | 85.5-88 | BMW 300s 81-90<br>Ford Sierra<br>MB W124<br>VW Golf 8.81-91   | Bosch                   |
| Alternator sliding ring       |          | 82-85.0 | BMW 300s 75-81<br>MB W123 76-80<br>VW Golf 74-7.81<br>Volvo 200-s 74-8.81   | Bosch                   |
| Alternator sliding ring       |          | 85.5-88 | BMW 300s 81-90<br>Ford Sierra<br>MB W124<br>VW Golf 8.81-91   | Bosch                   |
| Alternator belt               | L=735    | 82-85.0 | Peugeot 605 TD-2.1 -94 LA<br>Rover 75 1,8 LA<br>Rover Freelander 1,8 LA   |                         |
| Alternator belt, cars with AC |          | 82-85.0 | BMW 535/540 E39 ilmastointi<br>Mazda 626 1.6/2.0 85-87 LA/OT<br>Toyota Carina E 2,0 -93 LA<br>Toyota Picnic 2,0 VL/ei ILM |                         |
| Alternator belt               | 6x725mm  | 85.5-91 | Nissan Sunny GTi-16V  |                         |



## Porsche 944 951 968 Spare Parts and Cross Reference

|                                  |          |                      |   |                      |                           |                                    |
|----------------------------------|----------|----------------------|---|----------------------|---------------------------|------------------------------------|
|                                  |          |                      | 1,6/1,8 86-91 LA<br>Nissan Bluebird 1.6-2.0 86-88<br>LA<br>Nissan Prairie 2.0 88-89 LA  |                      |                           |                                    |
| Alternator belt,<br>cars with AC | L=1005mm | 85.5-91              | Citroen Jumper 2,5D/TD/TDi<br>LA+OT<br>MB 208D/210D/308D/310D -<br>95 LA<br>MB 408D/410D -95 LA<br>Peugeot Boxer 2,5D/TD/TDi<br>LA+OT |                      |                           |                                    |
| Windshield<br>washer pump        |          | 82-91                | VW Golf I/II/III  |                      |                           |                                    |
| Reverse light<br>switch          |          | 82-91                | MB 100D<br>MB 207D-310D (601/602) 80-<br>95<br>MB 407D-410D (611) 82-95   |                      |                           |                                    |
| Ignition coil                    |          | 82-91 <b>968</b>     | 911/928/924/944/968   | 0 221 118 322        | 944 602 115<br>01         | Bosch                              |
| Distributor rotor                |          | 944/951 (ei<br>S/S2) |   | 0 300 900 169        | 944 602 901<br>01         | Beru (EVL 169)                     |
| <b>Distributor Rotor</b>         |          | <b>968</b>           |   | <b>1 234 332 389</b> | <b>944 602 213<br/>01</b> | <b>Beru EVL 174<br/>Breml 7031</b> |
| Turn signal, side                |          | 82-91                | Golf I / II   |                      |                           |                                    |
| Starter motor<br>brushes         |          |                      | Audi 100  |                      |                           |                                    |
| Spark plug                       |          | 944/951 82-91        | Bosch WR7DC<br>NGK BPR6ES   |                      |                           |                                    |
| Spark plug                       |          | S2                   | NGK BPR7ES  |                      |                           |                                    |
| Ignition control<br>unit         |          | 944S/S2              | Ford Escort 1,6i 86-90<br>Opel Corsa 1,2N/1,4 87  |                      |                           | Bosch                              |

## Porsche 944 951 968 Spare Parts and Cross Reference

|                                 |                    |  |                                |                   |  |
|---------------------------------|--------------------|--|--------------------------------|-------------------|--|
|                                 |                    | Saab 900i-16V 85-93<br>Seat Ibiza 1,5i   |                                |                   |  |
| Turn signal relay               | 82-91              | Audi A6<br>BMW 316-320 9.79-90<br>Ford Sierra 82-93<br>Opel Astra<br>VW Golf III 91-98 | 0 335 200 041                  |                   | Bosch  |
| Distributor cap                 | 944/951 (NOT S/S2) |  | 1 235 522 325<br>0 330 920 414 | 944 602 251<br>00 | Bosch<br>Beru (VK 442 S)   |
| Distributor cap                 | 944S / S2          | Volvo B200/230   |                                |                   |  |
| Distributor cap                 | 968                |  | 1 235 522 395                  | 928 602 211<br>01 | Beru VK177s<br>(0330920331)<br>QUINTON HAZELL<br><a href="#">XD151</a> |
| Distributor dust cover          | 82-89              |  | 1 230 500 219                  | 944 602 803<br>00 | Bosch  |
| <a href="#">Ignition switch</a> | 82-85.0            | Golf I / II 74-92  |                                |                   |  |

Washer Pump Alternative **4A0 955 651 B Audi A8**, will require a rewire and new plug